

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2017 Levee Inspection Results

Reclamation District No. 0349 Sutter Island

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Reclamation District No. 0349 Sutter Island

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.59
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/26/2017 - 4/26/2017			
DWR Inspector	Herman Phillips			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start		Rating **	M	Issue No.	3
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0349_01_f_2014_3				
Comment Code					
Inspector Comment					
Was not able to see flood fight material storage location. The President of the District was not available with me on this inspection.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0349_01_f_2014_4				
Comment Code					
Inspector Comment					
RD 349 has O&M Manual on hand.					

No Photos

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0349_01_f_2014_14				
Comment Code					
Inspector Comment					
RD 349 does not have a crew, only landowners and farmers. Was not able to determine if they have been trained recently.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.00	Rating **	U	Issue No.	15
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.327148 °	38.313078 °
				-121.576952 °	-121.578780 °
DWR ID	DWR_RD0349_01_f_2016_15				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the wild growth of vegetation on the landside levee slope.					

Photo 1 of 1 : SP_2017_RD0349_204_15_20170426_00024.jpg



RD 349 Unit 1 levee mile 0.00 looking downstream landside slope.

LM Start	0.01	Rating **	U	Issue No.	20
LM End	0.94	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.327073 °	38.313798 °
				-121.576945 °	-121.578953 °
DWR ID	DWR_RD0349_01_s_2016_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the unwanted wild growth of brush and other vegetation from the waterside slope. Unable to see the ground.					

Photo 1 of 1 : SP_2017_RD0349_204_20_20170426_00025.jpg



RD 349 Unit 1 Levee mile 0.01 waterside shoulder looking downstream.

LM Start	0.03	Rating **	M	Issue No.	7
LM End	0.10	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.326743 °	38.325844 °
				-121.576979 °	-121.577119 °
DWR ID	DWR_RD0349_01_s_2016_7				
Comment Code					
Inspector Comment					
2015: Erosion observed at the toe. [2015 Site ID: SAC_33-9_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.04	Rating **	U	Issue No.	11
LM End	0.04	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.326638 °	38.326638 °
				-121.577001 °	-121.577001 °
DWR ID	DWR_RD0349_01_s_2017_11				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the dead fallen tree from the waterside levee section.					

Photo 1 of 1 : SP_2017_RD0349_204_11_20170516_00026.jpg



Waterside slope fallen dead tree branches cut up and remains on the levee slope.

LM Start	0.08	Rating **	M	Issue No.	22
LM End	0.08	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.326133 °	38.326133 °
				-121.577141 °	-121.577141 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44303 DS_ID:24137 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Pipe appears to be abandoned and if so should be done so properly. Electromagnetic survey indicated a crossing at this location. FIELD_STRUCT_DESC: *ABANDONED* 10-inch pipe through the levee, 3.8 feet below the crown. Power pole and anchor on the landward side. Deteriorated concrete box at the LS toe. Concrete debris on WS toe good indicator of pump location (USACE-1960). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.74). FS Date: 4/2/2015					

Photo 1 of 3 : UCIP_SP_2017_44303_73622.jpg



Deteriorated concrete distribution box on LS toe next to power pole.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017


Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.08	Rating **	M	Issue No.	22 (cont)	
LM End	0.08	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.326133 °		38.326133 °
				-121.577141 °		-121.577141 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44303						
DS_ID:24137						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Pipe appears to be abandoned and if so should be done so properly. Electromagnetic survey indicated a crossing at this location.						
FIELD_STRUCT_DESC: *ABANDONED* 10-inch pipe through the levee, 3.8 feet below the crown. Power pole and anchor on the landward side. Deteriorated concrete box at the LS toe. Concrete debris on WS toe good indicator of pump location (USACE-1960). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.74).						
FS Date: 4/2/2015						

LM Start	0.08	Rating **	M	Issue No.	22 (cont)
LM End	0.08	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_44303_73621.jpg



Concrete debris on WS toe is a good indicator of pump location.

Photo 3 of 3 : UCIP_SP_2017_44303_73620.jpg



Concrete debris on WS toe is a good indicator of pump location.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.48	Rating **	M	Issue No.	23
LM End	0.48	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.320476 °	38.320476 °
				-121.578616 °	-121.578616 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50062 DS_ID:24139 EP_NO: 951 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 8/22/2016 Meet Fred Wheeler with RD349 at this crossing. Crossing is active. Crossing was downgraded from Urgent to Non-Urgent -- no signs of pipe failure visible on surface. Need to contact owner -- dense vegetation on WS and LS should be cleared prior to next inspection. Need to coordinate with owner regarding the 8-inch sleeved pipe--need permit number to update record. (DWR UCIP - omagana)3/18/2009 Exposed section of levee slope on LS--need to contact owner and DWR inspector. Burrow activity noticed at crossing 10 inch holes. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. (DWR UCIP - omagana) FIELD_STRUCT_DESC: 8-inch steel pipe measured (instead of 10-inch) sleeved through a 12-inch steel pipe, 6.6 feet below the crown. Annular gap grouted at both ends. Active centrifugal pump on platform at landside (LS) toe. Inactive slant pump on steel platform on waterside slope (not present in 2008 referenced in USACE O&M manual). Exposed section pipe on WS slope. Service pole on the LS slope. (10-inch pipe sleeved through pre-existing 12-pipe under Permit No. 3382, 1960 - Davis J. Eliot and Son; 12-inch pipe authorized in under Permit No. 951, 1944 - Stillwater Orgards Company). [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, (HLM 0.5)]. FS Date: 8/17/2016					

Photo 1 of 3 : UCIP_SP_2017_50062_36547.jpg



View of pipe on WS with rip rap on toe--dense vegetation on slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.48	Rating **	M	Issue No.	23 (cont)
LM End	0.48	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.320476 °	38.320476 °
				-121.578616 °	-121.578616 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50062 DS_ID:24139 EP_NO: 951 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 8/22/2016 Meet Fred Wheeler with RD349 at this crossing. Crossing is active. Crossing was downgraded from Urgent to Non-Urgent -- no signs of pipe failure visible on surface. Need to contact owner -- dense vegetation on WS and LS should be cleared prior to next inspection. Need to coordinate with owner regarding the 8-inch sleeved pipe--need permit number to update record. (DWR UCIP - omagana)3/18/2009 Exposed section of levee slope on LS--need to contact owner and DWR inspector. Burrow activity noticed at crossing 10 inch holes. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. (DWR UCIP - omagana) FIELD_STRUCT_DESC: 8-inch steel pipe measured (instead of 10-inch) sleeved through a 12-inch steel pipe, 6.6 feet below the crown. Annular gap grouted at both ends. Active centrifugal pump on platform at landside (LS) toe. Inactive slant pump on steel platform on waterside slope (not present in 2008 referenced in USACE O&M manual). Exposed section pipe on WS slope. Service pole on the LS slope. (10-inch pipe sleeved through pre-existing 12-pipe under Permit No. 3382, 1960 - Davis J. Eliot and Son; 12-inch pipe authorized in under Permit No. 951, 1944 - Stillwater Orgards Company). [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, (HLM 0.5)]. FS Date: 8/17/2016					

Photo 2 of 3 : UCIP_SP_2017_50062_36546.jpg



View of pipe on LS--open cut section.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.48	Rating **	M	Issue No.	23 (cont)
LM End	0.48	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.320476 °	38.320476 °
				-121.578616 °	-121.578616 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50062 DS_ID:24139 EP_NO: 951 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 8/22/2016 Meet Fred Wheeler with RD349 at this crossing. Crossing is active. Crossing was downgraded from Urgent to Non-Urgent -- no signs of pipe failure visible on surface. Need to contact owner -- dense vegetation on WS and LS should be cleared prior to next inspection. Need to coordinate with owner regarding the 8-inch sleeved pipe--need permit number to update record. (DWR UCIP - omagana)3/18/2009 Exposed section of levee slope on LS--need to contact owner and DWR inspector. Burrow activity noticed at crossing 10 inch holes. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. (DWR UCIP - omagana) FIELD_STRUCT_DESC: 8-inch steel pipe measured (instead of 10-inch) sleeved through a 12-inch steel pipe, 6.6 feet below the crown. Annular gap grouted at both ends. Active centrifugal pump on platform at landside (LS) toe. Inactive slant pump on steel platform on waterside slope (not present in 2008 referenced in USACE O&M manual). Exposed section pipe on WS slope. Service pole on the LS slope. (10-inch pipe sleeved through pre-existing 12-pipe under Permit No. 3382, 1960 - Davis J. Eliot and Son; 12-inch pipe authorized in under Permit No. 951, 1944 - Stillwater Orgards Company). [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, (HLM 0.5)]. FS Date: 8/17/2016					

Photo 3 of 3 : UCIP_SP_2017_50062_36548.jpg



Dense burrow activity--10 inch hole present.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017


Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.88	Rating **	M	Issue No.	24
LM End	0.88	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.314672 °	38.314672 °
				-121.579102 °	-121.579102 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21572 DS_ID:24521 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No records were found during intial desk study--need to contact owner to obtain permit number authorizing work. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 8-inch pipe through the levee, 13.9 feet below the crown. Pump on platform at landward toe. Service pole on landward slope. FS Date: 3/18/2009					

LM Start	0.88	Rating **	M	Issue No.	24 (cont)
LM End	0.88	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_21572_36576.jpg



View of pipe crossing located on waterward side--dense vegetation on levee slope.

Photo 2 of 3 : UCIP_SP_2017_21572_36573.jpg



Pump house located on landward side at toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.88	Rating **	M	Issue No.	24 (cont)
LM End	0.88	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.314672 °	38.314672 °
				-121.579102 °	-121.579102 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21572 DS_ID:24521 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No records were found during intial desk study--need to contact owner to obtain permit number authorizing work. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 8-inch pipe through the levee, 13.9 feet below the crown. Pump on platform at landward toe. Service pole on landward slope. FS Date: 3/18/2009					

Photo 3 of 3 : UCIP_SP_2017_21572_36578.jpg



View of pump house, concrete stand pipe, and utility pole.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.03	Rating **	M	Issue No.	25
LM End	1.03	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.312496 °	38.312496 °
				-121.578625 °	-121.578625 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50013
DS_ID:24140
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 8/22/2016 Crossing has been downgraded from Urgent to Non-Urgent no signs of pipe failure were visible during site inspection. Minor erosion visible on LS shoulder covered by dry leaves. No permit was found--need to contact owner to determine age of crossing and determine when the last internal inspection was completed. (DWR UCIP - omagana)8/13/2009 Exposed section of levee slope on LS--need to contact owner and DWR inspector. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 14-inch pipe (waterside (WS) shoulder) and 12-inch pipe (landside (LS) shoulder) through the levee, 4.7 feet below the crown. Gate valve on the WS slope. Pump in pumphouse on LS slope. Pressure breaker behind pumphouse. Pipe exposed on WS slope. [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, HLM 1.1]
FS Date: 8/17/2016

LM Start	1.03	Rating **	M	Issue No.	25 (cont)
LM End	1.03	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_50013_36561.jpg



View of pipe on WS.

Photo 2 of 3 : UCIP_SP_2017_50013_36558.jpg



View of LS slope--open cut.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.03	Rating **	M	Issue No.	25 (cont)	
LM End	1.03	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.312496 °	38.312496 °	
				-121.578625 °	-121.578625 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50013 DS_ID:24140 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 8/22/2016 Crossing has been downgraded from Urgent to Non-Urgent no signs of pipe failure were visible during site inspection. Minor erosion visible on LS shoulder covered by dry leaves. No permit was found--need to contact owner to determine age of crossing and determine when the last internal inspection was completed. (DWR UCIP - omagana)8/13/2009 Exposed section of levee slope on LS--need to contact owner and DWR inspector. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. (DWR UCIP - omagana) FIELD_STRUCT_DESC: 14-inch pipe (waterside (WS) shoulder) and 12-inch pipe (landside (LS) shoulder) through the levee, 4.7 feet below the crown. Gate valve on the WS slope. Pump in pumphouse on LS slope. Pressure breaker behind pumphouse. Pipe exposed on WS slope. [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, HLM 1.1] FS Date: 8/17/2016						

Photo 3 of 3 : UCIP_SP_2017_50013_36556.jpg



View of LS: pump house, concrete stand pipe, and electric pole.

LM Start	1.06	Rating **	U	Issue No.	16
LM End	1.24	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.311992 °	38.309635 °
				-121.578460 °	-121.577285 °
DWR ID	DWR_RD0349_01_f_2016_16				
Comment Code					
V6 : Landscaping					
Inspector Comment					
The landscaping along levee mile 1.06-1.24 is unmaintained and completely blocking the view of landside levee slope.					

Photo 1 of 1 : SP_2017_RD0349_204_16_20170516_00027.jpg



RF 349 Unit 1 levee mile 1.06-1.24.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.19	Rating **	M	Issue No.	26
LM End	1.19	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.310287 °	38.310287 °
				-121.577669 °	-121.577669 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44304					
DS_ID:24141					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: 2007 DWR erosion repair site location?--need to find out fate of crossing. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.					
FIELD_STRUCT_DESC: *ABANDONED* Pumphouse at landward toe. Pressure breaker on landward side. Electromagnetic Survey indicated a crossing at this location as well.					
FS Date: 4/2/2015					

LM Start	1.19	Rating **	M	Issue No.	26 (cont)
LM End	1.19	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_44304_36580.jpg



Geotech fabric and protective frame at tree--design features of erosion repair site 2007-2009.

Photo 2 of 3 : UCIP_SP_2017_44304_73625.jpg



Pumphouse on LS toe (From google view)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.19	Rating **	M	Issue No.	26 (cont)	
LM End	1.19	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.310287 °	38.310287 °	
				-121.577669 °	-121.577669 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44304						
DS_ID:24141						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: 2007 DWR erosion repair site location?--need to find out fate of crossing. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.						
FIELD_STRUCT_DESC: *ABANDONED* Pumphouse at landward toe. Pressure breaker on landward side. Electromagnetic Survey indicated a crossing at this location as well.						
FS Date: 4/2/2015						

Photo 3 of 3 : UCIP_SP_2017_44304_73680.jpg



Pump and motor inside pumphouse at LS toe. No pipe visible.

LM Start	1.24	Rating **	M	Issue No.	10
LM End	1.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.309635 °	38.305938 °
				-121.577290 °	-121.574802 °
DWR ID	DWR_RD0349_01_f_2014_10				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Thin the tree growth so the slope can be seen during inspection.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.46	Rating **	M	Issue No.	27
LM End	1.46	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.306760 °	38.306760 °	
			-121.575312 °	-121.575312 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:44214
DS_ID:24143
EP_NO: 12005
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Pipe open on WS slope. 2007 Erosion Repair Site location?--Need to contact owner to determine if crossing is still in use. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: 6-inch steel irrigation pipe, 4.0 feet below the crown. Siphon breaker and protective housing at levee shoulder. Pump on waterward side. Pipe exposed on waterward slope, extending to pump. Discharge structure at landward toe. (Permit No. 12005-1977)
FS Date: 4/2/2015

LM Start	1.46	Rating **	M	Issue No.	27 (cont)
LM End	1.46	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_44214_36572.jpg



View of landward side.

Photo 2 of 3 : UCIP_SP_2017_44214_36571.jpg



Pipe located on landward side--unable to determine whether it belongs to crossing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.46	Rating **	M	Issue No.	27 (cont)	
LM End	1.46	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.306760 °	38.306760 °	
				-121.575312 °	-121.575312 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44214 DS_ID:24143 EP_NO: 12005 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe open on WS slope. 2007 Erosion Repair Site location?--Need to contact owner to determine if crossing is still in use. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 6-inch steel irrigation pipe, 4.0 feet below the crown. Siphon breaker and protective housing at levee shoulder. Pump on waterward side. Pipe exposed on waterward slope, extending to pump. Discharge structure at landward toe. (Permit No. 12005-1977) FS Date: 4/2/2015						

Photo 3 of 3 : UCIP_SP_2017_44214_36570.jpg



View of pipe at waterward shoulder with control box.

LM Start	1.53	Rating **	M	Issue No.	21	
LM End	1.56	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.305883 °		38.305450 °
				-121.574765 °		-121.574657 °
DWR ID	DWR_RD0349_01_f_2015_21					
Comment Code						
V2 : Remove the wild growth other than native grasses from the levee slopes.						
Inspector Comment						
Remove the growth from the waterside slope.						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.54	Rating **	U	Issue No.	12
LM End	1.54	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.305722 °	38.305722 °
				-121.574680 °	-121.574695 °
DWR ID	DWR_RD0349_01_f_2014_12				
Comment Code					
RW : Retaining Wall					
Inspector Comment					
This issue is under review with the CVFPB. No change.					

Photo 1 of 1 : SP_2017_RD0349_204_12_20170404_00001.jpg



Looking downstream at levee mile 1.55 unauthorized block wall placed on landward levee section, no CVFPB Permit.

LM Start	1.56	Rating **	U	Issue No.	13
LM End	1.58	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.305450 °	38.305162 °
				-121.574687 °	-121.574750 °
DWR ID	DWR_RD0349_01_f_2014_13				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
This Arundo present on the waterward section is blocking the view of the levee section. Remove it from the shoulder and slope. This Arundo is so thick the entire slope is completely blocked from view.					

Photo 1 of 1 : SP_2017_RD0349_204_13_20170404_00002.jpg



RD 349 Unit 1 waterside shoulder and slope levee mile 1.56-1.58.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Reclamation District No. 0349 Sutter Island

Waterway			Bank	Unit Miles
Unit No. 02 Steamboat Slough			Right	4.32
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/26/2017 - 4/26/2017			
DWR Inspector	Herman Phillips			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.00	Rating **	M	Issue No.	86
LM End	0.00	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.305124 °	38.305124 °
				-121.574772 °	-121.574772 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46168 DS_ID:25096 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to identify permit for crossing. FIELD_STRUCT_DESC: 2-inch waterline through the levee at an unknown depth below crown. Pipe provides service to bridge and beach (per landowner). FS Date: 4/9/2015					

Photo 1 of 3 : UCIP_SP_2017_46168_74542.jpg



Cut in pavement good indicator of pipe location.

LM Start	0.00	Rating **	M	Issue No.	86 (cont)
LM End	0.00	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_46168_74543.jpg



Christy box on WS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.00	Rating **	M	Issue No.	86 (cont)
LM End	0.00	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.305124 °	38.305124 °
				-121.574772 °	-121.574772 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46168 DS_ID:25096 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to identify permit for crossing. FIELD_STRUCT_DESC: 2-inch waterline through the levee at an unknown depth below crown. Pipe provides service to bridge and beach (per landowner). FS Date: 4/9/2015					

Photo 3 of 3 : UCIP_SP_2017_46168_74544.jpg



Pipe visible next to bridge on WS shoulder.

LM Start	0.01	Rating **	U	Issue No.	4
LM End	0.01	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.304870 °	38.304870 °
				121.574730 °	121.574730 °
DWR ID	DWR_RD0349_02_s_2012_4				
Comment Code					
BU : Building					
Inspector Comment					
This encroachment is along the waterward shoulder and was not authorized by the CVFPB. There are multiple encroachments at this site. Owner was working with CVFPB to get permits as of 11-2013. This issue is still pending as of 2016. No change. 5-2017.					

Photo 1 of 2 : SP_2017_RD0349_205_4_20170404_00006.jpg



Unauthorized building waterside shoulder; Unit 2 Sutter Slough.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.01	Rating **	U	Issue No.	4 (cont)	
LM End	0.01	Issue Type +	En	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.304870 °		38.304870 °
				121.574730 °		121.574730 °
DWR ID	DWR_RD0349_02_s_2012_4					
Comment Code						
BU : Building						
Inspector Comment						
This encroachment is along the waterward shoulder and was not authorized by the CVFPB. There are multiple encroachments at this site. Owner was working with CVFPB to get permits as of 11-2013. This issue is still pending as of 2016. No change. 5-2017.						

Photo 2 of 2 : SP_2017_RD0349_205_4_20170404_00007.jpg



Unauthorized fence adjacent to building waterside Sutter Slough.

LM Start	0.03	Rating **	U	Issue No.	34
LM End	1.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.304993 °	38.289043 °
				-121.575160 °	-121.584015 °
DWR ID	DWR_RD0349_02_f_2016_34				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses and weeds from the slope and berm.					

Photo 1 of 1 : SP_2017_RD0349_205_34_20170516_00082.jpg



RD 349 Unit 2 landside.

LM Start	0.04	Rating **	U	Issue No.	37
LM End	0.52	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.304928 °	38.300007 °
				-121.575310 °	-121.581023 °
DWR ID	DWR_RD0349_02_s_2017_37				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Spray and mow the waterside slope and shoulder.					

Photo 1 of 1 : SP_2017_RD0349_205_37_20170516_00083.jpg



RD 349 Unit 2 looking at the waterside slope and shoulder.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.04	Rating **	M	Issue No.	87
LM End	0.04	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.304885 °	38.304885 °
				-121.575369 °	-121.575369 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46169 DS_ID:25098 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be done so properly. Need to identify permit. FIELD_STRUCT_DESC: 1-inch waterline through the levee 1.5-feet below the crown. Pipe visible at fence on WS slope. FS Date: 4/9/2015					

Photo 1 of 3 : UCIP_SP_2017_46169_74545.jpg



Pipe visible at base of fence on WS shoulder.

LM Start	0.04	Rating **	M	Issue No.	87 (cont)
LM End	0.04	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_46169_74546.jpg



Fence on WS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.04	Rating **	M	Issue No.	87 (cont)
LM End	0.04	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.304885 °	38.304885 °
				-121.575369 °	-121.575369 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46169 DS_ID:25098 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be done so properly. Need to identify permit. FIELD_STRUCT_DESC: 1-inch waterline through the levee 1.5-feet below the crown. Pipe visible at fence on WS slope. FS Date: 4/9/2015					

Photo 3 of 3 : UCIP_SP_2017_46169_74547.jpg



Approximate location of pipe alignment on LS of crown.

LM Start	0.10	Rating **	M	Issue No.	88
LM End	0.10	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.304606 °	38.304606 °
				-121.576323 °	-121.576323 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21576 DS_ID:24145 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 10-inch pipe through the levee, 6.0 feet below the crown. Pump and slide gate on the waterward slope. Concrete pipe riser and distribution box at the landward toe. Service pole and anchor on the landward slope. FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21576_36593.jpg



Dense vegetation on waterward slope--2 pipes and 1 conduit.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.10	Rating **	M	Issue No.	88 (cont)
LM End	0.10	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.304606 °	38.304606 °
				-121.576323 °	-121.576323 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:21576
DS_ID:24145
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: *ABANDONED* 10-inch pipe through the levee, 6.0 feet below the crown. Pump and slide gate on the waterward slope. Concrete pipe riser and distribution box at the landward toe. Service pole and anchor on the landward slope.
FS Date: 3/18/2009

LM Start	0.10	Rating **	M	Issue No.	88 (cont)
LM End	0.10	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_21576_36592.jpg



Pipes through levee at waterward slope.

Photo 3 of 3 : UCIP_SP_2017_21576_36591.jpg



Multiple appurtenances found on landward side-standpipe, electrical pole, valve, concrete distribution box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.10	Rating **	M	Issue No.	89
LM End	0.10	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.304606 °	38.304606 °
				-121.576323 °	-121.576323 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21577					
DS_ID:24146					
EP_NO: 2480					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the landward slope.					
Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.					
FIELD_STRUCT_DESC: 10-inch steel pipe through the levee, 6.0 feet below the crown. Pump and slide gate on the waterward slope.					
Concrete pipe riser and distribution box with gate valve at the landward toe. Service pole and anchor on the landward slope. (Permit No. 2480-1959)					
FS Date: 3/18/2009					

LM Start	0.10	Rating **	M	Issue No.	89 (cont)
LM End	0.10	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_21577_36597.jpg



Dense vegetation on waterward slope-2 pipes and 1 conduit.

Photo 2 of 3 : UCIP_SP_2017_21577_36596.jpg



View of waterward side--pump and raised platform.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.10	Rating **	M	Issue No.	89 (cont)	
LM End	0.10	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.304606 °	38.304606 °	
				-121.576323 °	-121.576323 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:21577						
DS_ID:24146						
EP_NO: 2480						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the landward slope.						
Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.						
FIELD_STRUCT_DESC: 10-inch steel pipe through the levee, 6.0 feet below the crown. Pump and slide gate on the waterward slope.						
Concrete pipe riser and distribution box with gate valve at the landward toe. Service pole and anchor on the landward slope. (Permit No. 2480-1959)						
FS Date: 3/18/2009						

Photo 3 of 3 : UCIP_SP_2017_21577_36598.jpg



Pipes through levee at waterward slope.

LM Start	0.11	Rating **	M	Issue No.	46
LM End	0.11	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.304450 °	38.304450 °
				-121.576562 °	-121.576562 °
DWR ID	DWR_RD0349_02_s_2016_46				
Comment Code					
EQ : Equipment					
Inspector Comment					
Remove the equipment away from the levee toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.12	Rating **	M	Issue No.	6
LM End	0.12	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.304443 °	38.304443 °
				-121.576687 °	-121.576687 °
DWR ID	DWR_RD0349_02_f_2013_6				
Comment Code					
DE : Debris					
Inspector Comment					
Remove the trash from the levee section.					

No Photos

LM Start	0.13	Rating **	M	Issue No.	90
LM End	0.13	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.304345 °	38.304345 °
				-121.576824 °	-121.576824 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21613 DS_ID:24147 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 3-inch pipe through the levee, 3.3 feet below the crown. Gate valve on landward side. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 0.1). FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21613_36685.jpg



Underground service alert (USA) marking on levee crown.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Reclamation District No. 0349 Sutter Island

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.16	Rating **	M	Issue No.	73
LM End	0.16	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.304117 °	38.304117 °
				-121.577263 °	-121.577263 °
DWR ID	DWR_RD0349_02_s _ 2014_73				
Comment Code					
MA : Material					
Inspector Comment					
Remove the mateial from the landside levee section.					

No Photos

LM Start	0.21	Rating **	M	Issue No.	7
LM End	0.25	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.303673 °	38.303303 °
				-121.578065 °	-121.578695 °
DWR ID	DWR_RD0349_02_s _ 2012_7				
Comment Code					
V6 : Landscaping					
Inspector Comment					
The landscaping should be maintained or removed from the landside levee slope and shoulder.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.28	Rating **	M	Issue No.	91
LM End	0.28	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.303072 °	38.303072 °
				-121.579066 °	-121.579066 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:21614
DS_ID:24148
EP_NO: 12006
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Altered crossing--contact owner to obtain new permit authoring work. Debris remains on site. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: 6-inch steel irrigation pipe through the levee, 4.0 feet below the crown. 3-inch conduit through levee to service pump. Steel cutoff wall around pipe at center of levee. Siphon breaker in concrete riser at landward shoulder. Gate valve on landward side. Pump on concrete pad on waterward slope. Discharge structure at landward toe. (Permit No. 12006-1977)
FS Date: 3/18/2009

LM Start	0.28	Rating **	M	Issue No.	91 (cont)
LM End	0.28	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_21614_36691.jpg



View of landward side--unable to inspect.

Photo 2 of 3 : UCIP_SP_2017_21614_36690.jpg



Crossing has been altered--abandoned pipe through levee slope remains.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.28	Rating **	M	Issue No.	91 (cont)
LM End	0.28	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.303072 °	38.303072 °
				-121.579066 °	-121.579066 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21614 DS_ID:24148 EP_NO: 12006 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Altered crossing--contact owner to obtain new permit authoring work. Debris remains on site. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 6-inch steel irrigation pipe through the levee, 4.0 feet below the crown. 3-inch conduit through levee to service pump. Steel cutoff wall around pipe at center of levee. Siphon breaker in concrete riser at landward shoulder. Gate valve on landward side. Pump on concrete pad on waterward slope. Discharge structure at landward toe. (Permit No. 12006-1977) FS Date: 3/18/2009					

Photo 3 of 3 : UCIP_SP_2017_21614_36689.jpg



New configuration--sections of pipe have been abandoned.

LM Start	0.34	Rating **	M	Issue No.	9
LM End	0.39	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.302358 °	38.301772 °
				-121.579707 °	-121.580093 °
DWR ID	DWR_RD0349_02_s_2016_9				
Comment Code					
Inspector Comment					
2007 - Slow erosion, probably due to wave wash and fluvial erosion. Site has likely been here for awhile but was unseen due to boats parked in front. 2015: Large tree popout, scarp reaches crown of levee. [2015 Site ID: STM_25-8_R]					

Photo 1 of 1 : SP_2017_RD0349_205_9_20170404_00008.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.35	Rating **	U	Issue No.	39
LM End	0.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.302368 °	38.302368 °
				-121.579933 °	-121.579933 °
DWR ID	DWR_RD0349_02_s_2017_39				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
This erosion occurred during the Feb Storm 2017 event. This site need immediate attention,					

Photo 1 of 1 : SP_2017_RD0349_205_39_20170516_00086.jpg



RD 349 Unit 2 levee mile 0.35 waterside slope and shoulder.

LM Start	0.35	Rating **	M	Issue No.	38
LM End	0.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.302277 °	38.302277 °
				-121.579960 °	-121.579960 °
DWR ID	DWR_RD0349_02_s_2017_38				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree on the waterside slope cut up and remove from the levee section.					

No Photos

LM Start	0.45	Rating **	M	Issue No.	49
LM End	0.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.300990 °	38.300853 °
				-121.580678 °	-121.580748 °
DWR ID	DWR_RD0349_02_s_2016_49				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Thin out the trees to allow the slope to be seen.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.57	Rating **	M	Issue No.	62
LM End	3.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.299367 °	38.262782 °
				-121.581490 °	-121.591812 °
DWR ID	DWR_RD0349_02_f_2014_62				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the unwanted vegetation from the waterside slope.					

No Photos

LM Start	0.57	Rating **	M	Issue No.	92
LM End	0.57	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.299353 °	38.299353 °
				-121.581525 °	-121.581525 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21615 DS_ID:24149 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner (Permit No. 3678) to determine if crossing is still in use. If crossing is not in use will need to coordinate with DWR Inspector and CVFPB to remove pipe according to Title 23 requirements. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 6-inch irrigation pipe through the levee, 2.5 feet below the crown. Pump on waterward slope. Service pole at landward shoulder. 3-inch conduite through levee to service pump. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 0.6). Pump replaced and placed on concrete pad on waterward slope under Permit No. 3678 (1961). FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21615_36694.jpg



View of pipe and pump on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.57	Rating **	M	Issue No.	92 (cont)
LM End	0.57	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.299353 °	38.299353 °
				-121.581525 °	-121.581525 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:21615
DS_ID:24149
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to contact owner (Permit No. 3678) to determine if crossing is still in use. If crossing is not in use will need to coordinate with DWR Inspector and CVFPB to remove pipe according to Title 23 requirements. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: 6-inch irrigation pipe through the levee, 2.5 feet below the crown. Pump on waterward slope. Service pole at landward shoulder. 3-inch conduit through levee to service pump. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 0.6). Pump replaced and placed on concrete pad on waterward slope under Permit No. 3678 (1961).
FS Date: 3/18/2009

LM Start	0.57	Rating **	M	Issue No.	92 (cont)
LM End	0.57	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_21615_36695.jpg



View of landward shoulder--service pole and pipe section through slope.

Photo 3 of 3 : UCIP_SP_2017_21615_36696.jpg



View of landward side--it appears PVC pipe was sleeved through existing crossing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.60	Rating **	M	Issue No.	13
LM End	0.72	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.298897 °	38.297384 °
				-121.581571 °	-121.582176 °
DWR ID	DWR_RD0349_02_s_2016_13				
Comment Code					
Inspector Comment					
2010 - Small maintenance, erosion into the toe. 2011 - Minor new erosion at toe. 2015: Minor new erosion at toe, new tree popout. [2015 Site ID: STM_25-5_R]					

Photo 1 of 1 : SP_2017_RD0349_205_13_20170404_00011.jpg



USACE 2013 Photo #1

LM Start	0.82	Rating **	M	Issue No.	67
LM End	0.83	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.296005 °	38.295862 °
				-121.582838 °	-121.582900 °
DWR ID	DWR_RD0349_02_s_2012_67				
Comment Code					
MA : Material					
Inspector Comment					
Remove the material from the landward slope.					

No Photos

LM Start	0.83	Rating **	M	Issue No.	12
LM End	0.89	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.295753 °	38.294985 °
				-121.582838 °	-121.583147 °
DWR ID	DWR_RD0349_02_s_2012_12				
Comment Code					
V6 : Landscaping					
Inspector Comment					
The landscaping should be maintained.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.06	Rating **	M	Issue No.	35
LM End	1.06	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.292557 °	38.292557 °
				-121.583875 °	-121.583875 °
DWR ID	DWR_RD0349_02_f_2016_35				
Comment Code					
PI : Pipe					
Inspector Comment					
Old irrigation discarded pipe on landside slope need to be removed.					

Photo 1 of 1 : SP_2017_RD0349_205_35_20170404_00015.jpg



RD 349 Unit 2 levee mile 1.06 landside toe.

LM Start	1.08	Rating **	U	Issue No.	36
LM End	1.08	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.292380 °	38.292282 °
				-121.583963 °	-121.583958 °
DWR ID	DWR_RD0349_02_f_2016_36				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Land owner damaged the slope waterside. The damage need to be repaired soon as possible.					

Photo 1 of 2 : SP_2017_RD0349_205_36_20170404_00016.jpg



RD 349 Unit 2 waterside slope and berm Land owner has dug a pit.

LM Start	1.08	Rating **	U	Issue No.	36 (cont)
LM End	1.08	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2017_RD0349_205_36_20170404_00018.jpg



The landowner has knotted step into the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.33	Rating **	U	Issue No.	10
LM End	1.49	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.288727 °	38.286475 °
				-121.583823 °	-121.585026 °
DWR ID	DWR_RD0349_02_s_2016_10				
Comment Code					
Inspector Comment					
1997 - Erosion of very sandy levee behind large stand of riparian vegetation on top right bank. Dry ravel of sand. 1999 - Quarry waste rock was dumped down the levee slope; poor repair job; still eroding in places. Eroding at midslope off fabric. 2005 - Length revised, only the middle 150 - 200 ft are eroding. 2006 - Some rock/small material dumped down the bank but it is slowly unraveling. Upstream end is unraveling faster. Steep slope with poor gradation so fines are washing out. 2010 - Lots of overhanging trees and erosion pockets. 2011 - This site is upgraded to CRITICAL. Near vertical bank at the downstream end. New erosion at various locations throughout the site. 2015: No observed changes. [2015 Site ID: STM_24-7_R]					

Photo 1 of 1 : SP_2017_RD0349_205_10_20170404_00009.jpg



USACE 2013 Photo #1

LM Start	1.38	Rating **	M	Issue No.	93
LM End	1.38	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.287925 °	38.287925 °
				-121.584063 °	-121.584063 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21606 DS_ID:24154 EP_NO: 6274 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Crossing appears to have been altered--recommend coordinating with owner to determine records for crossing. Will need permit issued for pipe install. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 12-inch pipe through the levee, 3.0 feet below the crown. Cutoff wall around pipe at waterward shoulder. Siphon breaker at landward shoulder. Air vent and pressure breaker on waterward slope. Slant pump on the waterward slope. Concrete distribution box at landward toe. (Permit No. 6274-1974) FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21606_36655.jpg



View of abandoned framing located on river's edge.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

Reclamation District No. 0349 Sutter Island

Pipe sleeved through larger pipe.

Page 20 of 42

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.62	Rating **	M	Issue No.	94
LM End	1.62	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.285573 °	38.285573 °
				-121.586986 °	-121.586986 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:21607
DS_ID:24155
EP_NO: 1116
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: 8-inch steel irrigation pipe through the levee, 4.7 feet below the crown. Two concrete cutoff walls under each shoulder. Pressure breaker in concrete riser at levee shoulder. Pump on waterward side. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 1.7). Pipe reconstructed under Permit No. 1116 (1974).
FS Date: 3/18/2009

LM Start	1.62	Rating **	M	Issue No.	94 (cont)
LM End	1.62	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_21607_36661.jpg



View of waterward side.

Photo 2 of 3 : UCIP_SP_2017_21607_36659.jpg



Pipe at the waterward toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.62	Rating **	M	Issue No.	94 (cont)
LM End	1.62	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.285573 °	38.285573 °
				-121.586986 °	-121.586986 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21607 DS_ID:24155 EP_NO: 1116 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 8-inch steel irrigation pipe through the levee, 4.7 feet below the crown. Two concrete cutoff walls under each shoulder. Pressure breaker in concrete riser at levee shoulder. Pump on waterward side. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 1.7). Pipe reconstructed under Permit No. 1116 (1974). FS Date: 3/18/2009					

Photo 3 of 3 : UCIP_SP_2017_21607_36658.jpg



Filter system, control panel, and stand pipe located at the landward toe.

LM Start	1.77	Rating **	U	Issue No.	47
LM End	4.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.284002 °	38.254703 °
				-121.588933 °	-121.599700 °
DWR ID	DWR_RD0349_02_s_2017_47				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the wild growth other than native grasses from the landside levee slope.					

Photo 1 of 1 : SP_2017_RD0349_205_47_20170516_00088.jpg



RD 349 Unit 2 levee mile 1.77-3.79 landside slope and shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.83	Rating **	M	Issue No.	95
LM End	1.83	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.283238 °	38.283238 °
				-121.589337 °	-121.589337 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21608 DS_ID:24156 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 10-inch pipe through the levee, 3.9 feet below the crown. Siphon breaker in concrete riser on the landward shoulder. Pump and gate valve in pumphouse on the waterward slope. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 1.9). FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21608_36662.jpg



View of pipe on waterward slope.

LM Start	1.83	Rating **	M	Issue No.	95 (cont)
LM End	1.83	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_21608_36663.jpg



View of pipe daylight at shed on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.83	Rating **	M	Issue No.	95 (cont)	
LM End	1.83	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.283238 °	38.283238 °	
				-121.589337 °	-121.589337 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:21608						
DS_ID:24156						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.						
FIELD_STRUCT_DESC: 10-inch pipe through the levee, 3.9 feet below the crown. Siphon breaker in concrete riser on the landward shoulder. Pump and gate valve in pumphouse on the waterward slope. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 1.9).						
FS Date: 3/18/2009						

Photo 3 of 3 : UCIP_SP_2017_21608_36665.jpg



View inside pump house of pipe crossing coming out of levee.

LM Start	2.04	Rating **	M	Issue No.	19
LM End	2.05	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.280069 °	38.279919 °
				-121.589443 °	-121.589438 °
DWR ID	DWR_RD0349_02_s_2016_19				
Comment Code					
Inspector Comment					
2011 - Small scallop caused by erosion and wave wash. 2015: No observed changes. [2015 Site ID: STM_24-1_R]					

Photo 1 of 1 : SP_2017_RD0349_205_19_20170404_00013.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.11	Rating **	M	Issue No.	16
LM End	2.14	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.279017 °	38.278597 °
				-121.589615 °	-121.589854 °
DWR ID	DWR_RD0349_02_s_2016_16				
Comment Code					
Inspector Comment					
1997 - Top right bank has retreated into the levee. Site is between two rock sites. 1999 - Downstream half of the reach repaired with rock. 2000 - Trees leaning into the water. 2010 - Site appears worse. 2011 - New erosion at the toe. 2013 - Short vertical sections observed at upstream end. 2015: Minor new erosion. [2015 Site ID: STM_23-9_R]					

Photo 1 of 1 : SP_2017_RD0349_205_16_20170404_00012.jpg



USACE 2013 Photo #1

LM Start	2.15	Rating **	M	Issue No.	96
LM End	2.15	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.278682 °	38.278682 °
				-121.590104 °	-121.590104 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21609 DS_ID:24157 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Debris scattered--need to contact owner. If crossing is not in used will need to coordinate with DWR Inspector and CVFPB to remove per Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 8-inch pipe sleeved through 12-inch pipe through the levee, 4.0 feet below the crown. Annular gap not grouted. Service pole on the waterward shoulder. Pump on the waterward side. Concrete distribution box at landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.3). FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21609_36668.jpg



Inside view of distribution box located on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.15	Rating **	M	Issue No.	96 (cont)
LM End	2.15	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.278682 °	38.278682 °
				-121.590104 °	-121.590104 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:21609
DS_ID:24157
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Debris scattered--need to contact owner. If crossing is not in use will need to coordinate with DWR Inspector and CVFPB to remove per Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: 8-inch pipe sleeved through 12-inch pipe through the levee, 4.0 feet below the crown. Annular gap not grouted. Service pole on the waterward shoulder. Pump on the waterward side. Concrete distribution box at landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.3).
FS Date: 3/18/2009

LM Start	2.15	Rating **	M	Issue No.	96 (cont)
LM End	2.15	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_21609_36667.jpg



Debris along pipe alignment.

Photo 3 of 3 : UCIP_SP_2017_21609_36666.jpg



Overview of landward side--distribution box located at toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.39	Rating **	M	Issue No.	97
LM End	2.39	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.275493 °	38.275493 °
				-121.591208 °	-121.591208 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:39873					
DS_ID:24158					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Dense vegetation limit the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.					
FIELD_STRUCT_DESC: 12-inch pipe through the levee, 4.0 feet below the crown. Pump on pile structure on waterward side, walkway to pump. Concrete distribution box and power pole with anchor at landward toe. Concrete standpipe on landward side. (Permit No. 946, 1944). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.5).					
FS Date: 3/18/2009					

LM Start	2.39	Rating **	M	Issue No.	97 (cont)
LM End	2.39	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_39873_36678.jpg



View of waterward side--pump and control panel located on raised platform.

Photo 2 of 3 : UCIP_SP_2017_39873_36676.jpg



Overview of waterward side--dense vegetation limits slope inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.39	Rating **	M	Issue No.	97 (cont)
LM End	2.39	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.275493 °	38.275493 °
				-121.591208 °	-121.591208 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:39873					
DS_ID:24158					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Dense vegetation limit the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.					
FIELD_STRUCT_DESC: 12-inch pipe through the levee, 4.0 feet below the crown. Pump on pile structure on waterward side, walkway to pump. Concrete distribution box and power pole with anchor at landward toe. Concrete standpipe on landward side. (Permit No. 946, 1944). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.5).					
FS Date: 3/18/2009					

Photo 3 of 3 : UCIP_SP_2017_39873_36673.jpg



View of landward side--2 distribution boxes are located along pipe alignment.

LM Start	2.39	Rating **	U	Issue No.	1
LM End	2.39	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.275403 °	38.275403 °
				-121.591229 °	-121.591229 °
DWR ID	DWR_RD0349_02_f_2013_1				
Comment Code					
ST : Stairway					
Inspector Comment					
The landowner has installed steps on the waterside slope and has an unauthorized boat dock anchored to the waterside slope.					

Photo 1 of 3 : SP_2017_RD0349_205_1_20170404_00001.jpg



Unauthorized metal steps on the waterside levee slope at levee mile 2.39.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.39	Rating **	U	Issue No.	1 (cont)	
LM End	2.39	Issue Type +	En	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.275403 °		38.275403 °
				-121.591229 °		-121.591229 °
DWR ID	DWR_RD0349_02_f_2013_1					
Comment Code						
ST : Stairway						
Inspector Comment						
The landowner has installed steps on the waterside slope and has an unauthorized boat dock anchored to the waterside slope.						

Photo 2 of 3 : SP_2017_RD0349_205_1_20170404_00002.jpg



Unauthorized dock at waterside toe.

LM Start	2.39	Rating **	U	Issue No.	1 (cont)
LM End	2.39	Issue Type +	En	Location *	WS

Photo 3 of 3 : SP_2017_RD0349_205_1_20170404_00003.jpg



Unauthorized metal steps on the waterside slope levee mile 2.39.

LM Start	2.56	Rating **	M	Issue No.	3
LM End	2.69	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.273854 °	38.271998 °
				-121.588745 °	-121.589424 °
DWR ID	DWR_RD0349_02_s_2016_3				
Comment Code					
Inspector Comment					
2011 - Toe scour at the tidal zone. 2015: New tree popout and minor new erosion. [2015 Site ID: STM_23-6_R]					

Photo 1 of 2 : SP_2017_RD0349_205_3_20170404_00004.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.56	Rating **	M	Issue No.	3 (cont)	
LM End	2.69	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2015 USACE Erosion Survey, DRAFT			38.273854 °	38.271998 °	
				-121.588745 °	-121.589424 °	
DWR ID	DWR_RD0349_02_s_2016_3					
Comment Code						
Inspector Comment						
2011 - Toe scour at the tidal zone. 2015: New tree popout and minor new erosion. [2015 Site ID: STM_23-6_R]						

Photo 2 of 2 : SP_2017_RD0349_205_3_20170404_00005.jpg



USACE 2013 Photo #2

LM Start	2.93	Rating **	M	Issue No.	98
LM End	2.93	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.268674 °	38.268674 °
				-121.589419 °	-121.589419 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44328					
DS_ID:24159					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Pipe appears abandoned and should be done so properly.					
FIELD_STRUCT_DESC: *ABANDONED* 6-inch pipe through the levee, 1.5 feet below the crown. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 3.1).					
FS Date: 4/8/2015					

Photo 1 of 3 : UCIP_SP_2017_44328_73707.jpg



Pipe visible in water at WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.93	Rating **	M	Issue No.	98 (cont)	
LM End	2.93	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.268674 °	38.268674 °	
				-121.589419 °	-121.589419 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44328						
DS_ID:24159						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Pipe appears abandoned and should be done so properly.						
FIELD_STRUCT_DESC: *ABANDONED* 6-inch pipe through the levee, 1.5 feet below the crown. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 3.1).						
FS Date: 4/8/2015						

Photo 2 of 3 : UCIP_SP_2017_44328_73706.jpg



Pipe visible in water at WS toe.

LM Start	2.93	Rating **	M	Issue No.	98 (cont)
LM End	2.93	Issue Type +	En	Location *	WS

Photo 3 of 3 : UCIP_SP_2017_44328_73705.jpg



No pipe visible on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.00	Rating **	M	Issue No.	66
LM End	3.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.267710 °	38.267280 °
				-121.588828 °	-121.588613 °
DWR ID	DWR_RD0349_02_s_2016_66				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Thin the trees on the landside slope.					

No Photos

LM Start	3.02	Rating **	U	Issue No.	99
LM End	3.02	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.267471 °	38.267471 °
				-121.588659 °	-121.588659 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50015 DS_ID:24160 EP_NO: 655 Repair Type: Urgent Crossing Status: Found UCIP Comments: 8/17/2016 Dense vegetation limits the inspector's visibility to inspect levee section along pipe alignment. Previous inspection indicates holes visible on pipe wall. Need to contact owner to notify that pipe needs to be abandoned properly per Title 23 requirements. (DWR UCIP - omagana)4/8/2015 Pipe visible on WS slope and appears to be open. Pipe needs to be properly abandoned or verified as having been done so properly. (DWR UCIP - omagana) FIELD_STRUCT_DESC: *ABANDONED* 6-inch steel pipe through the levee, 3.7 feet below the crown. Pump on concrete blocks on the waterside (WS) slope. 2-inch galvanized conduit is buried along side of the 6-inch pipe. PG&E service was installed on the landside (LS). (6-inch pipe authorized under Permit No. 5350, 1966 - Enver Salman, 6-inch pipe replaced previous 8-inch pipe authorized under Permit No. 655, 1935 - M. S. Salman) Unable to confirm if 8-inch pipe is the same pipe listed in the USACE O&M manual as HLM 3.2. [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, HLM 3.2, Drawing No. 50-4-3042]. FS Date: 8/17/2016					

Photo 1 of 3 : UCIP_SP_2017_50015_73709.jpg



Abandoned pipe visible on slope in vegetation behind new pipe on WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.02	Rating **	U	Issue No.	99 (cont)
LM End	3.02	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.267471 °	38.267471 °
				-121.588659 °	-121.588659 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:50015 DS_ID:24160 EP_NO: 655 Repair Type: Urgent Crossing Status: Found UCIP Comments: 8/17/2016 Dense vegetation limits the inspector's visibility to inspect levee section along pipe alignment. Previous inspection indicates holes visible on pipe wall. Need to contact owner to notify that pipe needs to be abandoned properly per Title 23 requirements. (DWR UCIP - omagana)4/8/2015 Pipe visible on WS slope and appears to be open. Pipe needs to be properly abandoned or verified as having been done so properly. (DWR UCIP - omagana) FIELD_STRUCT_DESC: *ABANDONED* 6-inch steel pipe through the levee, 3.7 feet below the crown. Pump on concrete blocks on the waterside (WS) slope. 2-inch galvanized conduit is buried along side of the 6-inch pipe. PG&E service was installed on the landside (LS). (6-inch pipe authorized under Permit No. 5350, 1966 - Enver Salman, 6-inch pipe replaced previous 8-inch pipe authorized under Permit No. 655, 1935 - M. S. Salman) Unable to confirm if 8-inch pipe is the same pipe listed in the USACE O&M manual as HLM 3.2. [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, HLM 3.2, Drawing No. 50-4-3042]. FS Date: 8/17/2016					


LM Start	3.02	Rating **	U	Issue No.	99 (cont)
LM End	3.02	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_50015_73708.jpg



Abandoned pipe visible on slope in vegetation behind new pipe on WS slope.

Photo 3 of 3 : UCIP_SP_2017_50015_75632.jpg



Pipe visible from opposite bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.02	Rating **	M	Issue No.	100 (cont)	
LM End	3.02	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.267453 °		38.267453 °
				-121.588668 °		-121.588668 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44332 DS_ID:24199 EP_NO: 5350 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine if crossing is still in use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Debris scattered on slopes--remove. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 6-inch steel pipe and 2-inch iron electrical conduit through the levee, both 3.7 feet below the crown. Siphon breaker in pipe riser on waterward slope. Pump, switch panel, and butterfly valve on concrete blocks on the waterward slope. Service pole on landward slope (Permit No. 5350-1966). FS Date: 4/8/2015						

Photo 3 of 3 : UCIP_SP_2017_44332_73710.jpg



Butterfly valve next to, electrical panel, pump, and hand pump on WS slope.

LM Start	3.15	Rating **	M	Issue No.	101
LM End	3.15	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.265608 °	38.265608 °
				-121.588391 °	-121.588391 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46172 DS_ID:25099 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be verified as having been done so properly. FIELD_STRUCT_DESC: *ABANDONED* 6-inch pipe through the levee, 4.5 feet below the crown. Service pole at landward toe. FS Date: 4/2/2015					

Photo 1 of 3 : UCIP_SP_2017_46172_74553.jpg



Pipe just visible on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.15	Rating **	M	Issue No.	101 (cont)
LM End	3.15	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.265608 °	38.265608 °
				-121.588391 °	-121.588391 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46172 DS_ID:25099 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be verified as having been done so properly. FIELD_STRUCT_DESC: *ABANDONED* 6-inch pipe through the levee, 4.5 feet below the crown. Service pole at landward toe. FS Date: 4/2/2015					

Photo 2 of 3 : UCIP_SP_2017_46172_74554.jpg



View of WS from shoulder at crossing. Pipe not found on WS.

LM Start	3.15	Rating **	M	Issue No.	101 (cont)
LM End	3.15	Issue Type +	En	Location *	LS

Photo 3 of 3 : UCIP_SP_2017_46172_74555.jpg



Approximate pipe alignment on LS.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.31	Rating **	M	Issue No.	102
LM End	3.31	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.263359 °	38.263359 °
				-121.588721 °	-121.588721 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44333 DS_ID:24161 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 6-inch pipe through the levee, 4.5 feet below the crown. Pump and switch panel on the waterward slope. Service pole and concrete distribution box at landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 3.5). FS Date: 4/8/2015					

LM Start	3.31	Rating **	M	Issue No.	102 (cont)
LM End	3.31	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_44333_73713.jpg



Pipe, distribution box, and power pole visible on LS slope/toe.

Photo 2 of 3 : UCIP_SP_2017_44333_73712.jpg



distribution box and pipe visible on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.31	Rating **	M	Issue No.	102 (cont)	
LM End	3.31	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.263359 °		38.263359 °
				-121.588721 °		-121.588721 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44333 DS_ID:24161 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 6-inch pipe through the levee, 4.5 feet below the crown. Pump and switch panel on the waterward slope. Service pole and concrete distribution box at landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 3.5). FS Date: 4/8/2015						


Photo 3 of 3 : UCIP_SP_2017_44333_73711.jpg



Pipe and electrical conduit visible on WS slope.

LM Start	3.38	Rating **	M	Issue No.	11
LM End	3.49	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.262510 °	38.262533 °
				-121.589481 °	-121.591690 °
DWR ID	DWR_RD0349_02_s_2016_11				
Comment Code					
Inspector Comment					
2010 - Slumping sections on the lower bank, appears to be scouring around the trees. 2011 - Soil beach at toe. 2015: No observed changes. [2015 Site ID: STM_22-8_R]					

Photo 1 of 1 : SP_2017_RD0349_205_11_20170404_00010.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.58	Rating **	U	Issue No.	84
LM End	4.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.262588 °	38.254733 °
				-121.593328 °	-121.599963 °
DWR ID	DWR_RD0349_02_f_2015_84				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the snap grasses from the waterside levee slope.					

Photo 1 of 1 : SP_2017_RD0349_205_84_20170404_00027.jpg



Tall snap grasses covering the waterward slope. No change.

LM Start	3.69	Rating **	U	Issue No.	50
LM End	3.69	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.261578 °	38.261578 °
				-121.594820 °	-121.594820 °
DWR ID	DWR_RD0349_02_s_2017_50				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the fallen tree from the levee slope and remove the cut up fire wood from the shoulder landward.					

Photo 1 of 2 : SP_2017_RD0349_205_50_20170516_00089.jpg



Landside slope levee mile 3.69.

LM Start	3.69	Rating **	U	Issue No.	50 (cont)
LM End	3.69	Issue Type +	En	Location *	LS

Photo 2 of 2 : SP_2017_RD0349_205_50_20170516_00091.jpg



Landside shoulder and slope levee mile 3.69.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.72	Rating **	M	Issue No.	22
LM End	3.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.261111 °	38.261001 °
				-121.595062 °	-121.595052 °
DWR ID	DWR_RD0349_02_s_2012_22				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree limbs from the levee slope.					

No Photos

LM Start	3.76	Rating **	U	Issue No.	59
LM End	3.93	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.260596 °	38.258123 °
				-121.592160 °	-121.595150 °
DWR ID	DWR_RD0349_02_f_2013_59				
Comment Code					
FE : Fence					
Inspector Comment					
Inside the fenced off area are several pet shelters and pens for chickens and goats on the landside levee slope and toe. This need to be taken off the levee section. In the event of a flood fight this area would cause delays in response time.					

Photo 1 of 1 : SP_2017_RD0349_205_59_20170516_00092.jpg



Unauthorized electric fence installed along the shoulder and levee slope landside .

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.80	Rating **	M	Issue No.	103
LM End	3.80	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.260007 °	38.260007 °
				-121.595273 °	-121.595273 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21612 DS_ID:24162 EP_NO: 8188 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 12-inch steel irrigation pipe and 1.25-inch electrical conduit through the levee, both 5.0 feet below the crown. Steel cutoff wall around pipe at center of levee. Siphon breaker on shoulder. Pump and pumphouse on the waterward side. Service pole, discharge box and concrete standpipe at landward toe. (Permit No. 8188-1973) FS Date: 3/18/2009					

Photo 1 of 3 : UCIP_SP_2017_21612_36684.jpg



Overview of waterward side--2 crossings.

LM Start	3.80	Rating **	M	Issue No.	103 (cont)
LM End	3.80	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_21612_36682.jpg



View of crossing on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.32	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.80	Rating **	M	Issue No.	103 (cont)	
LM End	3.80	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.260007 °	38.260007 °	
				-121.595273 °	-121.595273 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:21612 DS_ID:24162 EP_NO: 8188 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the landward slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Unable to determine if crossing is in use. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 12-inch steel irrigation pipe and 1.25-inch electrical conduit through the levee, both 5.0 feet below the crown. Steel cutoff wall around pipe at center of levee. Siphon breaker on shoulder. Pump and pumphouse on the waterward side. Service pole, discharge box and concrete standpipe at landward toe. (Permit No. 8188-1973) FS Date: 3/18/2009						

Photo 3 of 3 : UCIP_SP_2017_21612_36683.jpg



Overview of lanward side--appurtenances include distribution box, stand pipe, pump house, and control panel.

LM Start	3.81	Rating **	M	Issue No.	85
LM End	3.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.259882 °	38.257252 °
				-121.595245 °	-121.595403 °
DWR ID	DWR_RD0349_02_f_2015_85				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Exterminate the rodents from the levee section.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2017 Levee Inspection Results

Reclamation District No. 0349 Sutter Island

Waterway			Bank	Unit Miles
Unit No. 03 Sutter Slough			Left	6.50
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/26/2017 - 4/26/2017			
DWR Inspector	Herman Phillips			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.00	Rating **	U	Issue No.	34
LM End	1.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.254752 °	38.275993 °
				-121.600067 °	-121.601013 °
DWR ID	DWR_RD0349_03_f_2016_34				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Tall weeds on the landside levee slope need to be removed from the levee section.					

Photo 1 of 1 : SP_2017_RD0349_206_34_20170522_00078.jpg



RD 349 Unit 4 levee mile 0.00 landside slope and shoulder.

LM Start	0.00	Rating **	U	Issue No.	35
LM End	2.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.254752 °	38.292205 °
				-121.600067 °	-121.603727 °
DWR ID	DWR_RD0349_03_f_2016_35				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Tall weeds on the waterside levee slope need to be removed.					

Photo 1 of 1 : SP_2017_RD0349_206_35_20170522_00079.jpg



RD 349 Unit 4 levee mile 0.00 waterside slope.

LM Start	0.04	Rating **	U	Issue No.	37
LM End	0.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.255327 °	38.255327 °
				-121.600033 °	-121.600033 °
DWR ID	DWR_RD0349_03_f_2016_37				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Dead tree on the waterside slope (large). This tree will fall and block access to the levee crown roadway. Remove the dead tree from the levee section.					

Photo 1 of 1 : SP_2017_RD0349_206_37_20170522_00077.jpg



RD 349 Unit 4 levee mile 0.04 Dead tree on the waterside shoulder and crown roadway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.17	Rating **	M	Issue No.	38
LM End	1.14	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.257200 °	38.270755 °
				-121.599772 °	-121.603570 °
DWR ID	DWR_RD0349_03_s_2017_38				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

LM Start	0.30	Rating **	M	Issue No.	59
LM End	0.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.259081 °	38.259081 °
				-121.600046 °	-121.600046 °
DWR ID	DWR_RD0349_03_s_2014_59				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree limb from the landside slope.					

No Photos

LM Start	0.69	Rating **	C	Issue No.	53
LM End	0.80	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.264615 °	38.266097 °
				-121.601382 °	-121.601822 °
DWR ID	DWR_RD0349_03_f_2016_53				
Comment Code					
FE : Fence					
Inspector Comment					
Remove the unauthorized electric fence from the landside shoulder and slope.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side WS : Water Side CR : Crown		A : Acceptable M : Minimally Acceptable U : Unacceptable		Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
N/A : Not Applicable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.77	Rating **	M	Issue No.	91
LM End	0.77	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.265751 °	38.265751 °
				-121.601655 °	-121.601655 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43442					
DS_ID:24163					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Need to find owner and notify of pipe deterioration.					
Owner will need to replace or remove per CVFPB Title 23 requirements.					
Dense vegetation limits the inspector's visibility to identify signs of pipe					
failure (leaks) through the levee slopes. Recommend removing					
vegetation along pipe alignment to conduct proper inspection of					
structure and appurtenances. Note date on photos should be 3/18/09					
not 7/26/08 camera metadata is incorrect.					
FIELD_STRUCT_DESC: 8-inch steel irrigation pipe through the levee,					
2.4 feet below the crown. Pump and gate valve in a pumphouse at the					
landward toe. Concrete standpipe on landward side.					
FS Date: 3/19/2009					

Photo 1 of 3 : UCIP_SP_2017_43442_36707.jpg



View of waterward side--portion of pipe exposed on slope.

LM Start	0.77	Rating **	M	Issue No.	91 (cont)
LM End	0.77	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_43442_36706.jpg



Pump house located at the landward toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.77	Rating **	M	Issue No.	91 (cont)
LM End	0.77	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.265751 °	38.265751 °
				-121.601655 °	-121.601655 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43442 DS_ID:24163 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to find owner and notify of pipe deterioration. Owner will need to replace or remove per CVFPB Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 8-inch steel irrigation pipe through the levee, 2.4 feet below the crown. Pump and gate valve in a pumphouse at the landward toe. Concrete standpipe on landward side. FS Date: 3/19/2009					

Photo 3 of 3 : UCIP_SP_2017_43442_36704.jpg



Pipe covered by dense vegetation.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.91	Rating **	M	Issue No.	92
LM End	0.91	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.267620 °	38.267620 °
				-121.602458 °	-121.602458 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21673 DS_ID:24232 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No records were found during initial desk study--need to contact owner to obtain permit number authorizing work. Unable to determine if filter system is part of crossing appurtenances. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 12-inch pipe through the levee, approximately 2.0 feet below the crown. Pipe changes diameter, 10-inch along both shoulders and 8-inch diameter exit on waterward side. Pipe exposed along both slopes. Pump on waterward side. Filtration system and power pole on landward side. Rock revetment on waterward slope. FS Date: 10/3/2013 9:42:00 AM					

LM Start	0.91	Rating **	M	Issue No.	92 (cont)
LM End	0.91	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_21673_36851.jpg



View of waterward side--pipe and pump.

Photo 2 of 3 : UCIP_SP_2017_21673_36853.jpg



View of pipe crossing past pump station.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	0.91	Rating **	M	Issue No.	92 (cont)	
LM End	0.91	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.267620 °		38.267620 °
				-121.602458 °		-121.602458 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:21673						
DS_ID:24232						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: No records were found during initial desk study--need to contact owner to obtain permit number authorizing work. Unable to determine if filter system is part of crossing appurtenances. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.						
FIELD_STRUCT_DESC: 12-inch pipe through the levee, approximately 2.0 feet below the crown. Pipe changes diameter, 10-inch along both shoulders and 8-inch diameter exit on waterward side. Pipe exposed along both slopes. Pump on waterward side. Filtration system and power pole on landward side. Rock revetment on waterward slope.						
FS Date: 10/3/2013 9:42:00 AM						

Photo 3 of 3 : UCIP_SP_2017_21673_36852.jpg



View of siphon breaker.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.17	Rating **	M	Issue No.	93
LM End	1.17	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.271218 °	38.271218 °
				-121.603468 °	-121.603468 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44335 DS_ID:24166 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe abandoned and should be done so properly or verified as having been done so properly. FIELD_STRUCT_DESC: 6-inch pipe through the levee, 4.5 feet below the crown. Pump and pumphouse no longer on the landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 1.2). FS Date: 4/9/2015					

Photo 1 of 2 : UCIP_SP_2017_44335_73721.jpg



Pipe visible on LS slope.

LM Start	1.17	Rating **	M	Issue No.	93 (cont)
LM End	1.17	Issue Type +	En	Location *	LS

Photo 2 of 2 : UCIP_SP_2017_44335_73720.jpg



Pipe visible on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.26	Rating **	M	Issue No.	94
LM End	1.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.272515 °	38.272515 °
				-121.603048 °	-121.603048 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:47043 DS_ID:24169 EP_NO: 11744 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 1 of 2: 8-inch pipe through the levee, 3.7 feet below the crown. 8-inch pipe is reduced to 3-inch pipe on waterward side. Steel cutoff wall around pipe at center of levee. Siphon breaker at landward shoulder. Siphon breaker at landward shoulder. Slant pump on waterward side. Discharge structure at landward toe. Rock revetment on waterward slope. (Permit No. 11744-1976) FS Date: 3/19/2009					

Photo 1 of 1 : UCIP_SP_2017_47043_36864.jpg



View of pipe, control panel, and stairs. 2 pipes go through levee 14-inch and 8-inch.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Reclamation District No. 0349 Sutter Island

Pipe reduced from 14-inch to 10-inch and conduit through levee.

Page 9 of 47

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.26	Rating **	M	Issue No.	95 (cont)	
LM End	1.26	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.272532 °	38.272532 °	
				-121.603039 °	-121.603039 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:47042 DS_ID:24168 EP_NO: 11744 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 2 of 2: 14-inch steel irrigation pipe and 2-inch electric conduit through the levee, both 4.4 feet below the crown. Reduced to 12-inch steel pipe under both levee slopes. Steel cutoff wall around pipe at center of levee. Siphon breaker at landward shoulder. Slant pump on waterward side with staircase access. Discharge structure at landward toe. Rock revetment on waterward slope. (Permit No. 11744-1976) FS Date: 3/19/2009						

Photo 3 of 3 : UCIP_SP_2017_47042_36858.jpg



Rip rap along the waterward toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.49	Rating **	M	Issue No.	96
LM End	1.49	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.275532 °	38.275532 °
				-121.601225 °	-121.601225 °

Comment Code

Inspector Comment

FS_ID:43446
DS_ID:24229
EP_NO: 2954
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: [R.D. No. 349 Drainage Pumping Plant] 1 of 3: 18-inch pipe through the levee, 7.8 feet below the crown. Siphon breakers on waterward slope. Pumps on platform on landward side.
FS Date: 3/19/2009

LM Start	1.49	Rating **	M	Issue No.	96 (cont)
LM End	1.49	Issue Type +	Ma	Location *	LS

Photo 1 of 2 : UCIP_SP_2017_43446_36725.jpg



Aerial map showing alignment of 18-inch pipe.

Photo 2 of 2 : UCIP_SP_2017_43446_36726.jpg



View of all 3 pipes through levee and visible on waterward toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.49	Rating **	M	Issue No.	97
LM End	1.49	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.275546°	38.275546°
				-121.601218°	-121.601218°

Comment Code

Inspector Comment

FS_ID:43445
DS_ID:24228
EP_NO: 2954
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: [R.D. No. 349 Drainage Pumping Plant] 2 of 3: 24-inch pipe through the levee, 7.8 feet below the crown. Siphon breakers on waterward slope. Pumps on platform on landward side.
FS Date: 3/19/2009

LM Start	1.49	Rating **	M	Issue No.	97 (cont)
LM End	1.49	Issue Type +	Ma	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_43445_36730.jpg



Enter photo 5 description or comment here.

Photo 2 of 3 : UCIP_SP_2017_43445_36727.jpg



View of pipe on waterward side--pipe running. Siphon breaker visible on pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.49	Rating **	M	Issue No.	97 (cont)	
LM End	1.49	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.275546 °		38.275546 °
				-121.601218 °		-121.601218 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:43445						
DS_ID:24228						
EP_NO: 2954						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.						
FIELD_STRUCT_DESC: [R.D. No. 349 Drainage Pumping Plant] 2 of 3: 24-inch pipe through the levee, 7.8 feet below the crown. Siphon breakers on waterward slope. Pumps on platform on landward side.						
FS Date: 3/19/2009						

Photo 3 of 3 : UCIP_SP_2017_43445_36728.jpg



Pipe is wrapped--unwrapped coating.

LM Start	1.49	Rating **	M	Issue No.	98
LM End	1.49	Issue Type +	Ma	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.275570 °	38.275570 °
				-121.601222 °	-121.601222 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21632					
DS_ID:24171					
EP_NO: 2954					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.					
FIELD_STRUCT_DESC: [R.D. No. 349 Drainage Pumping Plant] 3 of 3: 24-inch pipe through the levee, 7.8 feet below the crown. Metal cutoff wall around pipe at landward shoulder. Siphon breakers on waterward slope. Two anchor posts driven into levee on each side of pipe. Pumps on platform on landward side. (Permit No. 2954-1959)					
FS Date: 3/19/2009					

Photo 1 of 3 : UCIP_SP_2017_21632_36733.jpg



Aerial view of all 3 pipes through levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.49	Rating **	M	Issue No.	98 (cont)	
LM End	1.49	Issue Type +	Ma	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.275570 °	38.275570 °	
				-121.601222 °	-121.601222 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:21632 DS_ID:24171 EP_NO: 2954 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: [R.D. No. 349 Drainage Pumping Plant] 3 of 3: 24-inch pipe through the levee, 7.8 feet below the crown. Metal cutoff wall around pipe at landward shoulder. Siphon breakers on waterward slope. Two anchor posts driven into levee on each side of pipe. Pumps on platform on landward side. (Permit No. 2954-1959) FS Date: 3/19/2009						

LM Start	1.49	Rating **	M	Issue No.	98 (cont)
LM End	1.49	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_21632_36731.jpg



View of waterward side--2-24 inch pipes.

Photo 3 of 3 : UCIP_SP_2017_21632_36734.jpg



All 3 pipes visible on waterward side--tall grass limits inspection on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.52	Rating **	M	Issue No.	43
LM End	1.89	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.275993 °	38.281177 °
				-121.601010 °	-121.600830 °
DWR ID	DWR_RD0349_03_s_2017_43				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	1.82	Rating **	M	Issue No.	99
LM End	1.82	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.280199 °	38.280199 °
				-121.600500 °	-121.600500 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:47045					
DS_ID:24172					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes.					
Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.					
FIELD_STRUCT_DESC: 1 of 2: 12-inch pipe and 2-inch electrical conduit through the levee, both 8.0 feet below the crown. Siphon breaker in pipe riser on landward slope. Concrete standpipe at landward toe. Pump on waterward side with stairway access.					
FS Date: 3/19/2009					

Photo 1 of 3 : UCIP_SP_2017_47045_36736.jpg



View of waterward side--pump, pipe, control panel, and stairway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.82	Rating **	M	Issue No.	99 (cont)	
LM End	1.82	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.280199 °		38.280199 °
				-121.600500 °		-121.600500 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:47045 DS_ID:24172 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 1 of 2: 12-inch pipe and 2-inch electrical conduit through the levee, both 8.0 feet below the crown. Siphon breaker in pipe riser on landward slope. Concrete standpipe at landward toe. Pump on waterward side with stairway access. FS Date: 3/19/2009						

LM Start	1.82	Rating **	M	Issue No.	99 (cont)
LM End	1.82	Issue Type +	En	Location *	LS

Photo 2 of 3 : UCIP_SP_2017_47045_36735.jpg



Stand pipe located on landward shoulder--pipe locked.

Photo 3 of 3 : UCIP_SP_2017_47045_36737.jpg



Tall thin stand pipe located on landward side--unable to find pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	1.89	Rating **	U	Issue No.	47
LM End	6.33	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.281177 °	38.328778 °
				-121.600830 °	-121.579013 °
DWR ID	DWR_RD0349_03_s_2017_47				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses and weeds from the landside slope and berm.					

Photo 1 of 1 : SP_2017_RD0349_206_47_20170522_00076.jpg



RD 349 Unit 4 looking from levee mile 1.89 landside slope and berm.

LM Start	1.92	Rating **	M	Issue No.	2
LM End	1.97	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.310959 °	38.311288 °
				-121.597748 °	-121.596972 °
DWR ID	DWR_RD0349_03_s_2016_2				
Comment Code					
Inspector Comment					
2015: Tall vertical sections into the levee slope and erosion along the toe. [2015 Site ID: STR_26-1_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.00	Rating **	M	Issue No.	100
LM End	2.00	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.282498 °	38.282498 °
				-121.601758 °	-121.601758 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21634 DS_ID:24173 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 8-inch pipe through the levee, 6.7 feet below the crown. Pump in pumphouse and concrete standpipe at the landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.1). FS Date: 3/19/2009					

LM Start	2.00	Rating **	M	Issue No.	100 (cont)
LM End	2.00	Issue Type +	En	Location *	WS

Photo 1 of 2 : UCIP_SP_2017_21634_36739.jpg



View of landward side--pump house and stand pipe.

Photo 2 of 2 : UCIP_SP_2017_21634_36738.jpg



View of waterward side--dense vegetation limits inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.56	Rating **	M	Issue No.	101
LM End	2.56	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.289633 °	38.289633 °
				-121.603313 °	-121.603313 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:43423
DS_ID:24176
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to contact owner--If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: *ABANDONED* 10-inch pipe through the levee, 8.2 feet below the crown. Pipe has plate welded on the waterward end. 3-inch galvanized pipe runs parallel to 10-inch pipe. Abandoned tank on waterward slope. Distribution box and concrete standpipe at landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.7).
FS Date: 3/19/2009

LM Start	2.56	Rating **	M	Issue No.	101 (cont)
LM End	2.56	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_43423_36866.jpg



View of waterward side--dense vegetation covers slope.

Photo 2 of 3 : UCIP_SP_2017_43423_36865.jpg



Pipe visible on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.56	Rating **	M	Issue No.	101 (cont)	
LM End	2.56	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.289633 °	38.289633 °	
				-121.603313 °	-121.603313 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:43423 DS_ID:24176 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner--If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 10-inch pipe through the levee, 8.2 feet below the crown. Pipe has plate welded on the waterward end. 3-inch galvanized pipe runs parallel to 10-inch pipe. Abandoned tank on waterward slope. Distribution box and concrete standpipe at landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 2.7). FS Date: 3/19/2009						

Photo 3 of 3 : UCIP_SP_2017_43423_36867.jpg



Stand pipe located on landward toe.

LM Start	2.74	Rating **	M	Issue No.	40
LM End	3.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.292205 °	38.295762 °
				-121.603727 °	-121.604755 °
DWR ID	DWR_RD0349_03_f_2016_40				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
There is a veg site here that has not been maintained, the site is not managed and not maintained.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.77	Rating **	M	Issue No.	102
LM End	2.77	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.292557 °	38.292557 °
				-121.603767 °	-121.603767 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43424 DS_ID:24177 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 2007 Erosion Repair Site location?--Need to contact owner to determine if crossing is still in use. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 8-inch pipe through the levee, 8.7 feet below the crown. Headwall and gate valve on the landward side. FS Date: 3/19/2009					

LM Start	2.77	Rating **	M	Issue No.	102 (cont)
LM End	2.77	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_43424_36869.jpg



Waterward side--appears to be an erosion repair site. New pipe on waterward side and damaged pipe on landward side.

Photo 2 of 3 : UCIP_SP_2017_43424_36871.jpg



View of waterward side--headwall, pipe, and gate valve.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.77	Rating **	M	Issue No.	102 (cont)	
LM End	2.77	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.292557 °		38.292557 °
				-121.603767 °		-121.603767 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:43424 DS_ID:24177 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 2007 Erosion Repair Site location?--Need to contact owner to determine if crossing is still in use. If crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 8-inch pipe through the levee, 8.7 feet below the crown. Headwall and gate valve on the landward side. FS Date: 3/19/2009						

Photo 3 of 3 : UCIP_SP_2017_43424_36868.jpg



View of landward side--dense vegetation on slope limits inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.88	Rating **	U	Issue No.	103
LM End	2.88	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.294080 °	38.294080 °
				-121.604260 °	-121.604260 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50014
DS_ID:24178
EP_NO: 6321
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 8/17/2016 Unable to determine condition of crossing due to dense vegetation on both WS and LS. Need to contact owner to determine status of crossing. Unable to confirm if WS pipe capped with metal plate. (DWR UCIP - omagana)4/08/2015 Appears abandoned and if so should be done so properly. Pipe open at LS toe. Unable to verify if plate is welded over WS end. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: *ABANDONED* 8-inch steel irrigation pipe through the levee, 4.5 feet below the crown. Corrugated metal cutoff wall around pipe at center of levee. Siphon breaker is located on the waterside (WS) shoulder. Pump is located on the landside (LS). Gate valve is located on the WS. 1.5-inch filler pipe at same location. Plate welded to WS end (Permit No. 6321, 1969 - B.C. Wheeler).
FS Date: 8/17/2016

LM Start	2.88	Rating **	U	Issue No.	103 (cont)
LM End	2.88	Issue Type +	En	Location *	WS

Photo 1 of 3 : UCIP_SP_2017_50014_73743.jpg



Pipe and pump platform on LS toe.

Photo 2 of 3 : UCIP_SP_2017_50014_73742.jpg



1.5-inch filler pipe and 8-inch steel irrigation pipe at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	2.88	Rating **	U	Issue No.	103 (cont)	
LM End	2.88	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.294080 °	38.294080 °	
				-121.604260 °	-121.604260 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:50014 DS_ID:24178 EP_NO: 6321 Repair Type: Urgent Crossing Status: Found UCIP Comments: 8/17/2016 Unable to determine condition of crossing due to dense vegetation on both WS and LS. Need to contact owner to determine status of crossing. Unable to confirm if WS pipe capped with metal plate. (DWR UCIP - omagana)4/08/2015 Appears abandoned and if so should be done so properly. Pipe open at LS toe. Unable to verify if plate is welded over WS end. (DWR UCIP - omagana) FIELD_STRUCT_DESC: *ABANDONED* 8-inch steel irrigation pipe through the levee, 4.5 feet below the crown. Corrugated metal cutoff wall around pipe at center of levee. Siphon breaker is located on the waterside (WS) shoulder. Pump is located on the landside (LS). Gate valve is located on the WS. 1.5-inch filler pipe at same location. Plate welded to WS end (Permit No. 6321, 1969 - B.C. Wheeler). FS Date: 8/17/2016						

Photo 3 of 3 : UCIP_SP_2017_50014_73741.jpg



Abandoned pump at LS toe.

LM Start	3.01	Rating **	U	Issue No.	73
LM End	6.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.296033 °	38.328778 °
				-121.604735 °	-121.579013 °
DWR ID	DWR_RD0349_03_s_2017_73				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Control the annual grasses from the levee slope and shoulder.					

Photo 1 of 1 : SP_2017_RD0349_206_73_20170522_00080.jpg



RD 349 Unit 4 waterside shoulder and slope levee mile 3.01-6.33.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.34	Rating **	M	Issue No.	104
LM End	3.34	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.299703 °	38.299703 °
				-121.601112 °	-121.601112 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44389 DS_ID:24179 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Crossing altered--need to contact owner to obtain permit number authorizing work. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *DELETE* FS Date: 4/9/2015					

Photo 1 of 3 : UCIP_SP_2017_44389_36873.jpg



View of waterward side--pump, control panel, pipe, and walkway.

LM Start	3.34	Rating **	M	Issue No.	104 (cont)
LM End	3.34	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_44389_36875.jpg



Corrugated metal riser located on waterward toe.

* Location
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

** Rating
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 N : Not Inspected/Rated
 C : Corrected
 A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.34	Rating **	M	Issue No.	104 (cont)	
LM End	3.34	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.299703 °		38.299703 °
				-121.601112 °		-121.601112 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44389 DS_ID:24179 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Crossing altered--need to contact owner to obtain permit number authorizing work. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *DELETE* FS Date: 4/9/2015						

Photo 3 of 3 : UCIP_SP_2017_44389_36874.jpg



View of landward side.

LM Start	3.34	Rating **	M	Issue No.	105
LM End	3.34	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.299718 °	38.299718 °
				-121.601095 °	-121.601095 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44390					
DS_ID:24214					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Walway and pier abandoned and appears to be a hazard that should be removed.					
FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee 5.8-feet below the crown. Pump, butterfly valve, and electrical panel on WS slope. Pier and walkway next to pump on WS slope. Power pole, filters, and distribution box at LS toe.					
FS Date: 4/9/2015					

Photo 1 of 2 : UCIP_SP_2017_44390_73745.jpg



Pipe, filter system, powerpole, and distribution box at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.34	Rating **	M	Issue No.	105 (cont)	
LM End	3.34	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.299718 °	38.299718 °	
				-121.601095 °	-121.601095 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44390 DS_ID:24214 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Walway and pier abandoned and appears to be a hazard that should be removed. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee 5.8-feet below the crown. Pump, butterfly valve, and electrical panel on WS slope. Pier and walkway next to pump on WS slope. Power pole, filters, and distribution box at LS toe. FS Date: 4/9/2015						

Photo 2 of 2 : UCIP_SP_2017_44390_73746.jpg



Pump, electrical panel, butterfly valve, and walkway on WS slope.

LM Start	3.77	Rating **	M	Issue No.	106
LM End	3.77	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.305300 °	38.305300 °
				-121.598620 °	-121.598620 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:21644 DS_ID:24180 EP_NO: 9290 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. FIELD_STRUCT_DESC: 10-inch steel pipe and 1.5-inch steel electrical conduit through the levee, both 4.0 feet below the crown. Steel cutoff wall around pipe and conduit at center of levee. Pump and gate valve on waterward slope. 6-inch intake pipe extends from pump into channel. Distribution system at landward toe. (Permit No. 9290-1975) FS Date: 3/19/2009					

Photo 1 of 3 : UCIP_SP_2017_21644_36780.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.77	Rating **	M	Issue No.	106 (cont)	
LM End	3.77	Issue Type +	En	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			38.305300 °		38.305300 °
				-121.598620 °		-121.598620 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:21644						
DS_ID:24180						
EP_NO: 9290						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Dense vegetation limits the inspector's visibility to						
identify signs of pipe failure (leaks) through the levee slopes.						
Recommend removing vegetation along pipe alignment to conduct						
proper inspection of structure and appurtenances.						
FIELD_STRUCT_DESC: 10-inch steel pipe and 1.5-inch steel electrical						
conduit through the levee, both 4.0 feet below the crown. Steel cutoff						
wall around pipe and conduit at center of levee. Pump and gate valve						
on waterward slope. 6-inch intake pipe extends from pump into channel.						
Distribution system at landward toe. (Permit No. 9290-1975)						
FS Date: 3/19/2009						

LM Start	3.77	Rating **	M	Issue No.	106 (cont)
LM End	3.77	Issue Type +	En	Location *	WS

Photo 2 of 3 : UCIP_SP_2017_21644_36778.jpg



90 elbow at daylight and continues along slope and connects to pump.

Photo 3 of 3 : UCIP_SP_2017_21644_36781.jpg



Appurtenances located on waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.96	Rating **	M	Issue No.	107
LM End	3.96	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.307507 °	38.307507 °
				-121.596875 °	-121.596875 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43454					
DS_ID:24182					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Not Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes.					
Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.					
FIELD_STRUCT_DESC: *ABANDONED* 7-inch pipe through the levee, 2.0 feet below the crown.					
FS Date: 3/19/2009					

No Photos

LM Start	3.96	Rating **	M	Issue No.	108
LM End	3.96	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.307519 °	38.307519 °
				-121.596876 °	-121.596876 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43456					
DS_ID:24181					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Not Found					
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes.					
Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances.					
FIELD_STRUCT_DESC: *REMOVED* 10-inch pipe through the levee, 3.5 feet below the crown. Pump and gate valve in pumphouse at the landward toe. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 4.2). Removed and replaced with 10-inch pipe under Permit No. 15503 (1990).					
FS Date: 3/19/2009					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.96	Rating **	M	Issue No.	109
LM End	3.96	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.307533 °	38.307533 °
				-121.596881 °	-121.596881 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43455 DS_ID:24201 EP_NO: 15503 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee, 3.0 feet below the crown. Steel cutoff wall around pipe 24-inches landward of levee center. Pump and gate valve in pumphouse at the landward toe. Pipe is exposed along waterward slope. (Permit No. 15503-1990) FS Date: 3/19/2009					

Photo 1 of 2 : UCIP_SP_2017_43455_36783.jpg



Pump house located on landward side.

LM Start	3.96	Rating **	M	Issue No.	109 (cont)
LM End	3.96	Issue Type +	En	Location *	WS

Photo 2 of 2 : UCIP_SP_2017_43455_36782.jpg



View of waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	3.99	Rating **	U	Issue No.	50
LM End	6.33	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.307972 °	38.328778 °
				-121.597037 °	-121.579013 °
DWR ID	DWR_RD0349_03_s_2017_50				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					
Keep the crown roadway free of vegetation.					

Photo 1 of 1 : SP_2017_RD0349_206_50_20170522_00081.jpg



RD 349 Unit 4 levee mile 3.99 -6.33 crown roadway.

LM Start	3.99	Rating **	U	Issue No.	25
LM End	3.99	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.307997 °	38.307997 °
				-121.597039 °	-121.597039 °
DWR ID	DWR_RD0349_03_s_2012_25				
Comment Code					
FE : Fence					
Inspector Comment					
Unauthorized cable gate crossing levee. Cable gates crossing the levee crown have been prohibited. This encroachment should be removed.					

Photo 1 of 1 : SP_2017_RD0349_206_25_20170522_00082.jpg



Cable crossings has been banned. They are unauthorized.

LM Start	4.20	Rating **	M	Issue No.	78
LM End	4.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.310528 °	38.310528 °
				-121.597180 °	-121.597180 °
DWR ID	DWR_RD0349_03_f_2014_78				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					
Dead tree need removing from levee section.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.26	Rating **	M	Issue No.	110
LM End	4.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.310896 °	38.310896 °
				-121.596242 °	-121.596242 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43458 DS_ID:24183 EP_NO: 8681 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner to determine status of crossing. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 1 of 2: 6-inch steel pipe and 1.5-inch steel electrical conduit through the levee, 4.1 feet and 2.0 feet below the crown, respectively. Steel cutoff wall around pipe and conduit at center of levee. Pump on platform and gate valve on the waterward slope, not connected. Exposed suction pipe from pump to channel. Rock revetment on waterward slope. (Permit No. 8681-1973) FS Date: 3/19/2009					

Photo 1 of 1 : UCIP_SP_2017_43458_36784.jpg



View of waterward side. 2 crossing visible 12-inch and 6-inch pipes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.26	Rating **	M	Issue No.	111
LM End	4.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.310905 °	38.310905 °
				-121.596226 °	-121.596226 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43457 DS_ID:24184 EP_NO: 8681 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner. Is filter sytem located on landward side part of crossing. If so need permit number authorizing work. Also if crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 2 of 2: 12-inch steel irrigation pipe through the levee, 4.3 feet feet below the crown. Steel cutoff wall around pipe at center of levee. Pump on platform and gate valve on the waterward slope. Exposed suction pipe from pump to channel. Rock revetment on waterward slope. (Permit No. 8681-1973) FS Date: 3/19/2009					

LM Start	4.26	Rating **	M	Issue No.	111 (cont)
LM End	4.26	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_43457_36793.jpg



View of waterward side. 2 crossing visible 12-inch and 6-inch pipes.

Photo 2 of 3 : UCIP_SP_2017_43457_36792.jpg



Pump associated with 12-inch pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.26	Rating **	M	Issue No.	111 (cont)
LM End	4.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.310905 °	38.310905 °
				-121.596226 °	-121.596226 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43457 DS_ID:24184 EP_NO: 8681 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Need to contact owner. Is filter sytem located on landward side part of crossing. If so need permit number authorizing work. Also if crossing is no longer used by owner, the owner will need to coordinate with DWR Inspector and CVFPB to remove crossing according to Title 23 requirements. Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 2 of 2: 12-inch steel irrigation pipe through the levee, 4.3 feet feet below the crown. Steel cutoff wall around pipe at center of levee. Pump on platform and gate valve on the waterward slope. Exposed suction pipe from pump to channel. Rock revetment on waterward slope. (Permit No. 8681-1973) FS Date: 3/19/2009					

Photo 3 of 3 : UCIP_SP_2017_43457_36790.jpg



View of pipe and filter system on landward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.55	Rating **	M	Issue No.	112
LM End	4.55	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.313659 °	38.313659 °	
			-121.592159 °	-121.592159 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:43459
DS_ID:24185
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Recommend removing vegetation along pipe alignment. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: *ABANDONED* 10-inch steel irrigation pipe and 2-inch electrical conduit through the levee, both 2.8 feet below the crown. Abandoned pumps and gate valve on the waterward slope. Service pole on the landward slope. Concrete headwall on landward side. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 4.8).
FS Date: 3/19/2009

LM Start	4.55	Rating **	M	Issue No.	112 (cont)
LM End	4.55	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_43459_36796.jpg



Waterward side--pipe visible through dense vegetation.

Photo 2 of 3 : UCIP_SP_2017_43459_36795.jpg



Pump located on waterward side is not connected.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.55	Rating **	M	Issue No.	112 (cont)
LM End	4.55	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.313659 °	38.313659 °
				-121.592159 °	-121.592159 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:43459 DS_ID:24185 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No connection present--need to contact owner to determine if owner plans to use. If crossing is no longer in use owner will need to coordinate with DWR inspector and CVFPB to remove according to Title 23 requirements. Recommend removing vegetation along pipe alignment. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: *ABANDONED* 10-inch steel irrigation pipe and 2-inch electrical conduit through the levee, both 2.8 feet below the crown. Abandoned pumps and gate valve on the waterward slope. Service pole on the landward slope. Concrete headwall on landward sdie. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 4.8). FS Date: 3/19/2009					

Photo 3 of 3 : UCIP_SP_2017_43459_36797.jpg



Pipe on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.80	Rating **	M	Issue No.	113
LM End	4.80	Issue Type +	En	Location *	LS
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP Field Study		38.316968 °	38.316968 °	
			-121.590219 °	-121.590219 °	
DWR ID					

Comment Code

Inspector Comment

FS_ID:43431
DS_ID:24186
EP_NO: 15359
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect.
FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee, 6.0 feet below the crown. Siphon breaker in protective house at levee shoulder. Pump in pumphouse and power pole at landward toe. Pipe connected to 8-inch exposed pipe at landward shoulder, extending to pumphouse. Filter screen in channel at waterward toe. (Permit No. 15359-1990)
FS Date: 3/19/2009

LM Start	4.80	Rating **	M	Issue No.	113 (cont)
LM End	4.80	Issue Type +	En	Location *	LS

Photo 1 of 3 : UCIP_SP_2017_43431_36800.jpg



Air vent located on pipe on landward.

Photo 2 of 3 : UCIP_SP_2017_43431_36801.jpg



Pipe located on waterward side.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	4.80	Rating **	M	Issue No.	113 (cont)	
LM End	4.80	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.316968 °	38.316968 °	
				-121.590219 °	-121.590219 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:43431 DS_ID:24186 EP_NO: 15359 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Dense vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) through the levee slopes. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. FIELD_STRUCT_DESC: 10-inch steel irrigation pipe through the levee, 6.0 feet below the crown. Siphon breaker in protective house at levee shoulder. Pump in pumphouse and power pole at landward toe. Pipe connected to 8-inch exposed pipe at landward shoulder, extending to pumphouse. Filter screen in channel at waterward toe. (Permit No. 15359-1990) FS Date: 3/19/2009						

Photo 3 of 3 : UCIP_SP_2017_43431_36798.jpg



View of landward side.

LM Start	5.04	Rating **	M	Issue No.	42
LM End	5.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.320321 °	38.320321 °
				-121.589617 °	-121.589617 °
DWR ID	DWR_RD0349_03_f_2016_42				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
This elderberry bush here can be trimmed so the ground can be seen.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	5.06	Rating **	M	Issue No.	3
LM End	5.18	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.320491 °	38.322233 °
				-121.589927 °	-121.590127 °
DWR ID	DWR_RD0349_03_s_2016_3				
Comment Code					
Inspector Comment					
2015: Large Tree popout and tall vertical sections into the levee slope. [2015 Site ID: STR_26-9_L]					

No Photos

LM Start	5.14	Rating **	M	Issue No.	44
LM End	5.14	Issue Type +	En	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.321778 °	38.321778 °
				-121.589740 °	-121.589740 °
DWR ID	DWR_RD0349_03_s_2016_44				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree limbs from the crown roadway.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	5.19	Rating **	M	Issue No.	115
LM End	5.19	Issue Type +	En	Location *	CR
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.322460 °	38.322460 °
				-121.589690 °	-121.589690 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44391 DS_ID:24189 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: 4-inch pipe through the levee, 3.3 feet below the crown. Gate and pump on platform at the landward toe (missing). Platform on the waterward side. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 5.6). FS Date: 4/9/2015					

Photo 1 of 3 : UCIP_SP_2017_44391_73749.jpg



4-inch pipe next to larger pipe on LS slope.

LM Start	5.19	Rating **	M	Issue No.	115 (cont)
LM End	5.19	Issue Type +	En	Location *	CR

Photo 2 of 3 : UCIP_SP_2017_44391_73748.jpg



4-inch pipe next to larger pipe on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	5.19	Rating **	M	Issue No.	115 (cont)	
LM End	5.19	Issue Type +	En	Location *	CR	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			38.322460 °	38.322460 °	
				-121.589690 °	-121.589690 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:44391						
DS_ID:24189						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Appears abandoned and if so should be done so properly.						
FIELD_STRUCT_DESC: 4-inch pipe through the levee, 3.3 feet below the crown. Gate and pump on platform at the landward toe (missing). Platform on the waterward side. (USACE-1959). This entry matches the Drainage or Irrigation Structure referenced in O&M manual (HLM 5.6).						
FS Date: 4/9/2015						

Photo 3 of 3 : UCIP_SP_2017_44391_73747.jpg



Pier on WS toe.

LM Start	5.22	Rating **	M	Issue No.	21
LM End	5.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.322693 °	38.322693 °
				-121.589327 °	-121.589327 °
DWR ID	DWR_RD0349_03_s_2012_21				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					
Remove tree limbs over hanging roadway.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	5.25	Rating **	M	Issue No.	36
LM End	5.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.322868 °	38.322868 °
				-121.588868 °	-121.588868 °
DWR ID	DWR_RD0349_03_f_2012_36				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					
Remove tree limb hanging over roadway.					

No Photos

LM Start	5.57	Rating **	M	Issue No.	116
LM End	5.57	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.325845 °	38.325845 °
				-121.584890 °	-121.584890 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:44392 DS_ID:24191 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Electromagnetic survey indicated a crossing at this point. Appears abandoned and if so should be done so properly. FIELD_STRUCT_DESC: *ABANDONED* 3-inch pipe through the levee, 3.0 feet below the crown. FS Date: 3/19/2009					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Reclamation District No. 0349 Sutter Island

Page 44 of 47

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	5.58	Rating **	M	Issue No.	117 (cont)
LM End	5.58	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.326096 °	38.326096 °
				-121.584747 °	-121.584747 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50016
DS_ID:24190
EP_NO: 16077
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 8/22/2016 Crossing has been downgraded from Urgent to Non-Urgent no signs of pipe failure were present on levee crown or slopes during site visit. Need to contact owner to determine last internal inspection completed. (DWR UCIP - omagana)3/19/2009 Soil disturbed on landward slope--need to contact owner. Also vegetation limits the inspector's visibility to identify signs of pipe failure (leaks) along the slope. Recommend removing vegetation along pipe alignment to conduct proper inspection of structure and appurtenances. Note date on photos should be 3/18/09 not 7/26/08 camera metadata is incorrect. (DWR UCIP - omagana)
FIELD_STRUCT_DESC: 10-inch pipe through the levee, 3.8 feet below the crown. Pump in pumphouse on waterside (WS). Service pole on WS slope. Concrete standpipe and distribution box located on the WS toe. Pipe is exposed on both slopes. Section of pipe under crown, between shoulders, removed and replaced with 10-inch steel pipe in November 20, 1991, no permit application was filed. In August 13, 1993, Mr. Steve Makis of Flood Management, revealed that the pipe was not soil proofed, and siphon breaker was not installed, and backfill was less than 90 % and less than 2-foot of cover through the levee crown. Pipe was required to be completely removed and replaced in September 15, 1993. (10-inch authorized under Permit No. 16077, 1993 - John McCormack Company, 10-inch pipe replaces the USACE O&M 10-inch pipe referenced as HLM 5.9) [Additional Reference(s): DWR Levee Log, 2005. USACE San Joaquin O&M Manual Unit No. 110, May 1959, HLM 5.9, Drawing not available].
FS Date: 8/17/2016

Photo 2 of 3 : UCIP_SP_2017_50016_36843.jpg



View of pipe and pump along WS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

Reclamation District No. 0349 Sutter Island

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2017

Reclamation District No. 0349 Sutter Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.50	04/26/2017 04/26/2017	Herman Phillips

LM Start	5.83	Rating **	M	Issue No.	88
LM End	5.83	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.329465 °	38.329465 °
				-121.584995 °	-121.584995 °
DWR ID	DWR_RD0349_03_f_2014_88				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					
Trim the tree limb hanging over crown roadway.					

No Photos

LM Start	5.89	Rating **	M	Issue No.	90
LM End	5.89	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.330308 °	38.330308 °
				-121.584560 °	-121.584560 °
DWR ID	DWR_RD0349_03_f_2014_90				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					
Trim the tree limb hanging over crown roadway.					

No Photos

LM Start	6.09	Rating **	M	Issue No.	86
LM End	6.09	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.331327 °	38.331327 °
				-121.582067 °	-121.582067 °
DWR ID	DWR_RD0349_03_f_2014_86				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					
Trim the tree limb hanging over crown roadway.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--